



# Palmer Public Library Conditions Survey

6 5 5   S o u t h   V a l l e y   W a y  
P a l m e r ,   A l a s k a

## FOR REVIEW

Prepared by:  
Wolf Architecture, Inc  
625 South Cobb, Suite 200  
Palmer, Alaska 99645

**W O L F**  
ARCHITECTURE



August 3, 2023

**Table of Contents**

Executive Summary	3
Process	4
Exclusions / References	4-5
General Observations	6
Exterior Summary	7
Interior Summary	8
Mechanical Systems Summary	9-10
Electrical Systems Summary	11
Synopsis	11
Appendix	12-23

(Palmer Public Library Roof Collapse Report – PND Engineers)



*Palmer Public Library*

## **SECTION 01 :: EXECUTIVE SUMMARY**

On June 13, 2023, the design team convened at the Palmer Public Library to assess the existing state of the facility. The facility was damaged as a result of a partial collapse during a winter storm and remained unoccupied since that time. This report presents our observations and recommendations regarding the condition of the existing facility.

The Palmer Public Library is located at 655 South Valley Way on the northwest corner of the Palmer commons. The facility is accessed from a parking lot on the south and a service drive on the north.

The library is a single story wood frame and masonry structure constructed in 1984. The structure was designed under the provisions of the 1979 Uniform Building Code. The library is approximately 11,800 sf in total area, inclusive of a small fan mezzanine located within the roof structure. The facility was protected by a fully automatic sprinkler system.

The exterior walls of the building are constructed of load bearing concrete masonry units. The interior structure is a mix of wood bearing walls and steel posts supporting a glue-lam beam super structure which in turn supports the wood framed roof structure. A copy of the PND structural analysis is attached as an appendix to this report.



*Childrens Reading Area*

## PROCESS

The City of Palmer has commissioned this survey to support funding requests for planning purposes. The scope of this report includes:

1. Site and site access
2. Exterior finishes
3. Interior finishes
4. Structural systems
5. Mechanical systems
6. Electrical systems

No invasive procedures were used in this investigation. All recommendations are based on observation of the existing facility and supported by review of the construction drawings provided by the City of Palmer. Lidar imaging scanning of the interior and exterior surfaces, were performed as part of the site work using a lidar scanning camera.

## EXCLUSIONS


The condition assessment site observation was non-destructive and visual in nature. The following summarizes exclusions that should be assessed for future evaluations:

- **Invasive Procedures**
  - Finishes and building systems were not removed to evaluate underlying systems and finishes.

- **Observational Limitations**
  - Lifts and/or tall ladders were unavailable. Roofs and tall spaces were observed from the ground level. Ceiling elements and systems higher than approximately 9'-0" were not inspected beyond what was visible from the highest adjacent walking surface.
  - Areas that were not visible from normally accessible walking surfaces.
  - Exterior walls that would require roof access.
- **Hazmat and Geotechnical Evaluations**
  - Hazardous material evaluations were not completed. Based on the construction date, it can be assumed that the facility is free from hazardous materials.
  - Geotechnical evaluations were not performed.
- **Seismic Evaluation**
  - American Society of Civil Engineers (ASCE) 41-13 "Seismic Evaluation and Retrofit of Existing Buildings" Tier 1 screening was not performed.

## REFERENCES

- **Code**
  - 1979 Uniform Building Code
  - 2021 International Existing Building Code
  - 2021 International Building Code
- **Construction drawings**
  - Don Wycoff Architects, dated 4/09/1984.



## GENERAL OBSERVATIONS

### Site

The site is located in downtown Palmer, Alaska and is connected with paved streets and concrete sidewalks. A compliant accessible route has not been constructed from the parking lot to the library. However, generally speaking the site is relatively flat and creating an compliant accessible route could be easily achieved.

The service access is located on the northwest corner of the site and is accessed from East Dahlia Street. The finish floor at the service entrance is approximately 3 feet above grade and is accessed by a stair.

The existing facility is designed with earth berming on the north, south and west sides. The berming extends to the property line on the east side of the facility.



*Reception and Check Out*

## Architecture

The facility has had forty years of continuous use and the interior and exterior finishes, fixtures, and equipment are nearing or at an end of their anticipated serviceable life. The southern portion of the facility which includes the stack and reading areas is damaged beyond use and a complete reconstruction is required in these areas. Areas not immediately impacted by the roof collapse have been subsequently damaged because the building has remained exposed to the weather and has been without heat through winter temperature extremes. Any efforts to repair the damage to the facility will require the work be performed in accordance with the currently adopted model building codes as well as compliance with the Americans with Disabilities Act Guidelines. Building-wide renovations would include the replacement of mechanical systems, electrical systems majority of the finishes, accessories, doors, and casework throughout the facility.

## Exterior Finishes and Elements

Exterior finishes, soffits, trims, stairs, and ramps were observed to be in fair condition. Siding is a mix of painted wood clapboard siding and a prefinished steel seam roofing product. The lap siding is in fair condition and in need of repainting. The standing seam roofing product is also in fair condition. The paint system is weathered and chalking. The roof panels at the area of collapse are damaged. A means of accessing the roof was not available and close observation of the roof panels at the roof level was not possible. Water damage was not observable within the interior of the building except at the areas where collapse damage was evident. The roof assembly was designed as a “hot roof” and no means of natural ventilation was designed. A design of this type is in keeping with the state

of design practice in the 1980's. The build up of ice as a result of the roof design likely contributed to the roof collapse. During any redesign effort a ventilation strategy should be considered and implemented.

The existing hollow metal exterior doors are protected by overhangs, have been maintained, and are in fair condition. The doors and frames will require further evaluation relative to the replacement recommendation as part of a renovation. Door hardware should be replaced as part of any building renovation.

The windows are insulated painted wood and appear to be in relatively good condition with intact glazing seals. The windows are, however, forty years old and undoubtedly would be inefficient from an energy standpoint and it would be recommended the windows be replaced as part of any renovation.



*Check Out Desk*

### **Interior Finishes and Elements**

The interior space within the Library were well cared for by staff and patrons. However, interior finishes have been in use for forty years and are at the end of the anticipated serviceable product life. The damage associated with the building collapse has deteriorated the entire interior of the building. It is recommended that mold testing be conducted as part of any renovation to identify the presence of any mold resulting from the weather infiltration.

The interior finishes evaluated include flooring, wall finishes, doors, frames, and associated hardware, casework, washroom fixtures and accessories, and education furnishings and equipment.



## Structural System Summary

See attached PND Engineers structural assessment dated 2.28.2023.



*Mechanical Room*

## Mechanical System Summary

On Friday July 7, 2023, we performed a nondestructive walk through of the above-mentioned facility to ascertain the condition of the mechanical and plumbing systems. The result of this report shall detail the after effect of the snow-related roof collapse and the related freeze up of the interior of the building.

The plumbing system in the building consists of copper piping for the domestic water supply, cast iron waste and vent piping. Within the boiler room where the city water service is located, there are signs of pipe bursts. A complete inspection with pressure testing of the domestic water piping system would be required to verify the extent of piping damage.


The fire protection system consists of a 4" black steel pipe with branch piping serving the entire facility. In the area of the roof collapse, the piping has been destroyed beyond future use, it will all need to be replaced with new sprinkler heads and system balancing. The balance of the system in the building needs to be pressure tested to verify piping integrity. It is possible that the freeze up may have degraded portions of the piping system.

The heating system consists of two Lochinvar KBN400 boilers that are within 5 years of age. They appear to be in good condition, an actual startup will verify actual performance. The heating piping serving the building is comprised of copper piping supply heating medium. The system does not have a glycol tank or means of injecting glycol, indicating that water was the usable medium for heating. The expansion tank on the boiler loop has burst from the freeze up, further pressure testing of the piping system needs to occur to verify the integrity of the piping system. The hydronic piping serving the area of the roof collapse has been destroyed beyond use.

The ventilation system of the building is served by one air handler located on the main floor and a supply fan located in a penthouse area. The air handler appears to be in relatively good condition, but its age dates to 1984, this puts it at a point of it being near the end of its useful life.

The air handling system has variable air volume terminal units with hydronic reheat coils. There is a pad mounted air conditioning condensing unit located outside with refrigerant piping to a cooling coil located within the air handling unit. The unit is dated to 1984 as well, putting it at the end of its useful life. The ductwork and the associated variable air volume terminal units located in the area of the roof collapse has been destroyed beyond use.

It is recommended that the entire mechanical system be replaced as part of any renovation/reconstruction.



*Electrical Service*

## Electrical Systems Summary

The following is a summary of the findings and provides the basis for the recommendation.

1. The power, telecom, fire alarm, and lighting equipment and their associated wiring located within the area of the building in which the roof collapsed and been damaged beyond repair and cannot be salvaged for reuse.
2. The power, telecom, fire alarm, and lighting equipment and their associated wiring located outside of the area damaged by the roof collapse do not appear to be damaged. Although these building electrical systems may be in salvageable condition, they all appear to be 40 years old, putting the electrical equipment and electrical systems well past their recommended useful life. Due to their age, the existing equipment is either inefficient, unreliable, outdated, or all the above. Because of their age, we do not recommend salvaging any of the electrical systems for reuse.
3. The electric service is rated at 800 amps, 208 volts, 3 phase. Both the main disconnect and the metering enclosure are located indoors. The existing 800-amp electric service would likely be adequate to serve a new building of the same size. Increasing the building size would likely require increasing the electric service size. Current utility company standards require both the main disconnect and the CT enclosure to be located outside, so all three proposed projects would require a new electric service.

It is recommended that the entire electrical system be replaced as part of any renovation/reconstruction.

## Synopsis

The Palmer Library was in fair condition prior to the 2023 roof collapse but was nearing the end of life in terms of the anticipated lifespan of building systems and interior finishes. The roof collapse destroyed the reading and stack areas of the library, contributed to the further deterioration of the interior finishes, and resulted in the freezing of the entire heating, plumbing, and sprinkler systems. Given the age of the building, the electrical systems are also recommended to be replaced.

When considering the rehabilitation, reuse, and/or reconstruction of the existing facility the structure north of grid line 3 is by and large the only area of salvage, and it will likely require seismic upgrades as part of any renovation. Damage to the mechanical, electrical, and sprinkler systems will dictate that most if not all finishes will need to be removed. Programmatic changes within the facility will likely mandate some of the interior partitions to be removed.

In addition, any renovation will need to integrate accessibility mandates including a code required accessible route from an accessible parking space into and throughout the library.



# **PALMER PUBLIC LIBRARY ROOF COLLAPSE Structural Observation Report**

**February 28, 2023**

**PND Project Number: 231025**

**PREPARED FOR:**



**CITY OF PALMER**

**231 West Evergreen Avenue  
Palmer, Alaska 99645**

**PREPARED BY:**



**ENGINEERS, INC.**

**PND ENGINEERS, INC.**

**625 South Cobb Street Suite 202  
Palmer, Alaska 99645**


**PREPARED BY**

David Benti, P.E., S.E.  
Elizabeth Swan, P.E.  
Justin Lobdell, EIT

February 28, 2023  
PND Project No.: 231025

**CLIENT REPRESENTATIVE**

Jude Bilafer  
Public Works Director  
City of Palmer  
jbilafer@palmerak.org  
(907) 745-3400



PND Engineers, Inc. | Palmer Office

*David Benti*

David Benti, P.E., S.E.  
Principal

## **TABLE OF CONTENTS**

1. INTRODUCTION .....	1
2. BACKGROUND.....	1
3. RECCOMENDATIONS & CONCLUSIONS.....	7

# 1. INTRODUCTION

The roof of the Palmer Public Library suffered a partial collapse on February 15, 2023 at approximately 5:35 pm. The collapse occurred mainly over the children’s section of the library. However, surrounding areas were also impacted by the roof collapse. The City of Palmer engaged PND Engineers, Inc. (PND) to complete a structural observation of the building to document the extents of the visible damage, determine the cause of the collapse, if possible, and assess if the building is safe to enter to allow contractors to begin selective demolition, clean up and collection of building contents.

# 2. BACKGROUND

The Palmer Public Library is a single-story building, designed in 1984, that is approximately 11,500 square feet. The building is founded on a traditional concrete shallow foundation. The building uses a combination of concrete masonry unit (CMU) walls, steel columns and dimensional wood walls to support the wood framed roofs. The roof framing consists of glu-lam beams supporting engineered wood I-joists. The City of Palmer provided PND a complete set of record drawings for PND’s use and review. The record drawings indicate that the building was designed in accordance with the 1982 edition of the Uniform Building Code (UBC). The UBC was the building code used in many parts of the United States from 1927 to 1997. The UBC was replaced by the IBC after 1997.




Figure 1: Roof Framing Plan

The record drawings specify that the roof was designed for a uniform roof snow load of 40 pounds per square foot (psf). It is possible that the original library designers may have considered additional snow loading to account for potential snow drifts. Snow drift loads are additional loads applied to the structure in addition to the uniform roof snow load in to account for the extra weight present on the roof in areas

where snow drifts are likely to accumulate. There are no notes within the record drawings that indicate snow loads beyond the 40 psf uniform roof snow load were considered. Snow drifts were likely not included in the original analysis as the 1982 UBC did not include specific provisions for snow drift loading, as these requirements were not widely recognized as necessary for building safety until later. Under the currently adopted 2021 version of the International Building Code (IBC), the code required uniform roof snow load for Palmer is still 40 psf. However, modern codes also include provisions to account for snow drifts.

David Benti and Elizabeth Swan from PND Engineers visited the Palmer Public Library on February 21, 2023 to observe structural components of the interior and exterior of the building. PND surveyor, Andrew Hamilton, also visited the site to fly a remote-controlled drone with a camera to provide a closer observation of the collapsed roof from the exterior of the building. This allowed for a more complete observation of the collapsed low roof while maintaining a safe distance.



Photo 1: Elevation of Roof Collapse

From the exterior of the building, PND observed that the lower roof over the children’s section had separated from the glu-lam beam supports and collapsed inward (**Photo 1**). PND also noted that the high roof line above the collapsed lower roof was visibly sagging. The source of this sag was not immediately clear from the ground level observation. Video footage obtained via the drone, showed that the glu-lam support beams that supported the low and high roof had been broken along their lengths (**Photo 2**).



Photo 2: Annotated Elevation of Roof Collapse



The top half to two thirds of the glulam beams had collapsed with the low roof and only the lower portion of the glu-lam beams remained on the steel support columns. The loss of the top portion of the lower glulam beam left the high roof members without support and they settled until they came to rest on the remaining portion of the broken glu-lam beam. **Figure 2** shows a sketch of the structural section as observed from the record drawings which shows how the low and high roofs were supported by the glulam beam prior to the failure. **Figure 3** shows the approximate post-collapse position of the remaining framing.




Figure 2: Roof Section before Collapse




Figure 3: Roof Section After Collapse



Photo 3: Roof Snow Drift

PND was able to observe the snow drift on the intact portion of the low roof (**Photo 3**). The snow extends from the low roof up to the underside of the high roof overhangs making the snow drift approximately 3 feet deep. The drift appeared to have a very dense lower layer that was topped by two or more layers of softer drifted snow. PND was unable to gain safe access to this drift to take a weight measurement.

PND also reviewed the condition of the exterior CMU support wall. The wall was observed to be plumb and intact. No signs of damage or displacement were witnessed. Once the low roof debris is removed, a complete survey of the CMU wall should be performed.

PND entered the building from the loading dock entrance on the North side of the building and focused the initial observations on determining if the structural integrity of the high roof was sufficient to allow for safe movement further into the building to observe the area of collapse. Much of the library has hard lid ceilings which did not allow access for observation. In the areas where drop ceilings were present PND was able to remove ceiling tiles to see the structure above. The wood members above the ceiling grid



Photo 4: Beam Centered Over Column

were wrapped in gypsum wall board so a full observation of the members and their connections was not possible. However, PND was able to see that the beams were still centered over the interior columns and there was no evidence of large displacements of the roof beams along gridline 2 between grids C & D (**Photo 4**). PND recommends that the gypsum wall board in this area be removed to permit a full investigation of the area before other repairs are completed in the building. Based on the current limited review of this area, the beam and their connections appear to be intact.

PND was able to observe damage to the backside of the soffit framing over the circulation desk area from above the ceiling grid (**Photo 5**). This damage is the result of the high roof beams losing support along grid line 3 and dropping and crushing the soffits below. Since the soffit framing was firmly attached to the walls and columns below, they could not move downward without being crushed by the high roof (**Photo 6**). Much of this soffit framing is not

accessible for observation at this time. The soffit finishes should be removed in selected areas to allow for complete observation by an engineer before contractors begin clean up and repairs. This additional access will permit the engineer to determine the full extent of the damage and if the soffit needs to be removed to allow safe continued access to the area beneath it.



Photo 5: Damaged Soffit




Photo 6: Crushed Soffit



Photo 7: Collapsed Framing and Remaining Soffit

After assessing the high roof, PND shifted the focus to reviewing the area of low roof collapse. The low roof framing came to rest on top of the bookcases. Because the structure is still partially suspended, the collapsed framing is obscured by the remaining soffit that was framed below the roof before the collapse (**Photo 7**). PND was able to see that the top portions of the glulam beams, that broke away from the supports, were still attached to the low roof wood I-joists. The wood I-joists were still sitting within the light gauge steel top flange hangers (**Photo 8**). This observation meshes with the observations from the exterior of the building. PND was able to

observe some water staining on the beams due to past water exposure but PND did not witness any areas of wood rot during the site visit. The complete condition of the round steel support columns and high roof beams could not be ascertained since the elements were still covered with finishes. At least one steel column appeared to be deformed as viewed from the from the drone footage (**Photo 9**).



Photo 8: Joist in Top Flange Hangers



Photo 9: Damaged Steel Column

Figure 4 shows a roof plan from the building's record drawing with a summary of the damage observed during PND's site visit. This figure only identifies the areas of known damage. It is likely that additional damage will be discovered as building finishes are removed.




Figure 4: Summary of Observed Damage

### 3. RECCOMENDATIONS & CONCLUSIONS

After the site visit, PND performed calculations on the existing roof members to evaluate the expected capacity of the members when possible. The record drawings indicate that the low roof joists are Trus Joist TJI 45 series joists spaced at 16" on center. PND attempted to find legacy documents from the I-joist manufacturer to determine if these joists have the required capacity to support the uniform and snow drift loads. Unfortunately, PND was unable to find product data older than 1985 for the Trus Joist products. Therefore, PND could not verify the actual I-joist capacities per the original manufacturer. In the absence of this legacy data, PND chose to perform approximate calculations on joists by analyzing the modern-day joists that have the same flange dimensions as the joists observed in the field. The observed TJI 45 joists had 3-1/2" wide flanges which are similar to the modern I90 joists by Boise Cascade. Using this rough approximation, PND believes that the roof members were likely correctly sized for a uniform roof snow load of 40 psf. PND also reviewed the design of the of the low roof and high roof glu-lam beams and found that many of the members had very little reserve capacity left available after the application of the building self-weight and uniform snow load. PND then evaluated the low roof members with the

additional snow drift loading that would be required by the current building code. Current building code requires the application of a tapered snow drift over the 16.5 feet of low roof starting at the step between the high and low roofs along gridline 3. The snow drift adds 59 psf of snow load in addition to the 40 psf uniform snow drift and the tappers to zero over the 16.5 feet. **Figure 5** shows the snow drift diagram required by the current building codes. This drift loading was not required in the 1980s when the structure was designed. PND could not accurately review the 22" I-joists with the additional snow drift due to the lack of the legacy product data with the manufacturer's member capacities.




Figure 5: Code Required Snow Drift

With the additional snow drift loading, PND found that the 5-1/8" x 18" glu-lam beams supporting the low roof would be at 120% of their bending capacity. Even though the beams were found to be overstressed in bending, PND does not believe that this was the failure mechanism that led to the low roof collapse. The field observed damage to the beams does not appear to be from a bending failure. The beam failures appear to be the result of torsion on the glu-lam beams. The low roof joists were hung from one side of the glu-lam beam with top flange hangers. PND believes that the one-sided application of the high snow loads may have led to a rotational loading on the beams which exceeded their torsional capacity. Another possibility is that the low roof I-joists broke due to the high snow drift loading and the forces experienced during the collapse pulled the support beam apart. Both of these failure modes would have likely occurred before the glu-lam beams were overstressed in bending. Either of these failure modes would explain the observed longitudinal failures along the lengths of the support beams.

The failure of the lower roof glu-lam beams has left the high roof unsupported. PND strongly recommends that the high roof glu-lam beams be shored to provide support from the roof to the ground level before any recovery or repair efforts are conducted within the structure. Each high roof beam should be shored with either an 8x8 Douglas-Fir #1 timber post, a steel HSS4x4x5/16 column, or a steel shoring jack rated for 25,000 pounds. These posts shall be positively attached to the roof glu-lam beams and concrete slab to prevent movement during repairs. **Figure 6** shows the approximate locations of the recommended shoring posts. Once these shoring posts are in place, a contractor may begin to open up the damaged walls and soffits to allow a full observation of the structure. Once the full extent of the damage has been determined, the plans for cleanup and recovery of the structure may begin.




Figure 6: Approximate Shoring Locations

PND strongly recommends that the remaining snow drift on the low roof be removed by a qualified contractor prior to the commencement of other work. The removal of these drift will help migrate the potential for additional roof collapse. PND recommends the use of manlifts and/or roof rakes during the snow removal to minimize the personal on the roof as much as possible.

Finally, PND would like to emphasize that the extent of the structural roof damage exceeds thirty percent of the total roof area. Therefore, this classifies the roof damage as “substantial structural damage” per the International Existing Building Code (IEBC). Section 405.2.4 of the IEBC requires, “Gravity load-carrying components that have sustained substantial structural damage shall be rehabilitated to comply with the applicable provisions for dead and live loads in the International Building Code. Snow loads shall be considered if the substantial structural damage was caused by or related to snow load effects. Undamaged gravity load-carrying components that receive dead, live or snow loads from rehabilitated components shall also be rehabilitated if required to comply with the design loads of the rehabilitation design.” This code provision requires that any components requiring repair or elements that support components that require repair will need to be designed for the loading specified in the current edition of the IBC.